


LANGDON MITRE BOX CO., MILLERS FALLS, MASS.

PRICES OF PARTS OF NEW LANGDON AND NEW LANGDON IMPROVED.

		No. 1.	No. 2	N. 2 1/2.
20.	Swinging Lever,	\$1 25	—	—
21.	Legs,	15	15	15
22.	Stop Lever,	30	—	—
23.	Stop Gauge,	10	10	10
24.	Sliding Post,	—	50	85
25.	Stop Lever,	—	45	45
26.	Thumb Lever,	—	20	20
27.	Guide,	55	55	90
28.	Gib,	25	25	25
29.	Swinging Lever,	—	1 25	1 35
30.	Bed and Back,	1 45	1 45	1 60
31.	Thumb Screw,	10	10	10

Back for Panel Saw, 50 cts.



Parts of New Langdon Improved same as New Langdon, except circular guides and set screws for same.

Persons ordering parts will please state the number of the piece wanted, and the size of the machine for which it is designed, stating whether it is for **Langdon** or **New Langdon**. All parts of these Mitre Boxes are made to interchange, and will be sent by mail, if postage is sent with order. Postage, one cent for each ounce. Numbers 20, 29 and 30 are sent by express.


In ordering No. 27, please state size of Box, and whether front or back guide is wanted. Please preserve this card for reference in case of need. For parts of LANGDON MITRE BOX, see other side.

LANGDON MITRE BOX.

Mitre B. Size 1. Mitre B. Size 2. Mitre B. Size 2½. Mitre B. Size 3.

1.	Stop Gauge,	each	\$ 10	10	15	20
2.	Thumb Screw,	"	10	10	10	10
3.	Back Lever,	"	15	15	15	30
4.	Legs,	"	15	15	15	30
5.	Stop Lever,	"	30	—	—	—
6.	Stop Lever,	"	—	45	45	60
7.	Thumb Lever,	"	—	20	20	30
8.	Gib,	"	25	25	25	50
9.	Back,	"	30	30	50	60
10.	Back Posts,	"	35	35	60	70
11.	Saw Guides,	"	55	55	90	1 10
12.	Swinging Lever,	"	90	—	—	—
13.	Swinging Lever,	"	—	1 00	00	1 50
14.	Sliding Post,	"	—	50	85	1 00
15.	Bed,	"	1 00	1 00	1 00	2 00
	Bottom Board,	"	10	10	15	20
	Spiral Spring,	"	05	05	05	05
	Screws,	"	05	05	05	05
	Lever Pins,	"	05	05	05	05
	Set Screw,	"	—	10	10	10

In ordering Backs (No. 9), please state whether a Right or Left-hand Back is wanted. Parts of size "A" are four-fifths of the price of size 1. For parts of NEW LANGDON and NEW LANGDON IMPROVED MITRE BOX, see other side.



Parts of No. 15 cannot be mailed.